

# Store your Spare Spindles at the Spindle SPA

Having a spare spindle on-hand can keep your machine shop in production. But an unproperly stored spindle can end up costing you if not properly maintained. Corrosion and rust from moisturte in the air can cause damage to the bearings. Additionally, extended periods of sitting still can substantially compromise the bearing lubricant.

Treat your spindles to the Spindle SPA offered by Advanced Spindle Technology. Your spindle will be well cared for to ensure it's ready to go at a moments notice.

- Stored in temperature and humidity controlled room.
- 11 revolutions of spindle bimonthly.
- Ready to ship same day service!



### **Locations**

Southeast Service Facility

2709 Boulder Park Court Winston-Salem, NC 27101 Midwest Service Facility 318 Remington Road Cuyahoga Falls, OH 44223

Call: (833) 854-2579



WWW.ASTSPINDLES.COM



## Expert Analysis Repair & Response



Spindles are the most precise and heavily stressed component in a machine tool, making it the heart and soul of the operation. When a repair is needed, it requires specialized equipment and knowledge to evaluate, repair, and return it to service properly.

Advanced Spindle Technology has a team specializing in spindle diagnostics, maintenance, and repair services. Our experience allows us to address the needs of your company in a timely manner – getting your machines back in production quickly.

### **Our Repair Process**



**Receive**Discuss performance issues and expectations



**Evaluate**Complete analysis & provide firm quote



Repair
Utilize technology and experience to optimize performance



**Deliver** Return spindle FAST, Reducing downtime

#### **Convenient Locations**

Southeast Service Facility

2709 Boulder Park Court Winston-Salem, NC 27101 Midwest Service Facility 318 Remington Road Cuyahoga Falls, OH 44223

Call: (833) 854-2579

WWW.ASTSPINDLES.COM